


# HUDSON FASTENERS

## MEASUREMENT CONVERSION CHART

[www.HudsonFasteners.com](http://www.HudsonFasteners.com)

Email: [info@hudsonfasteners.com](mailto:info@hudsonfasteners.com)



**Toll-Free: 1-877-4-A-SCREW (1-877-427-2739)**

**TEL: 330-270-9500 | FAX: 330-270-5804**

Inch Fraction	Decimal	Metric mm
1/64 . . . . .	0.0156 . . . . .	0.3969
1/32 . . . . .	0.0313 . . . . .	0.7938
3/64 . . . . .	0.0469 . . . . .	1.1906
1/16 . . . . .	0.0625 . . . . .	1.5875
5/64 . . . . .	0.0781 . . . . .	1.9844
3/32 . . . . .	0.0938 . . . . .	2.3813
7/64 . . . . .	0.1094 . . . . .	2.7781
<b>1/8 . . . . .</b>	<b>0.1250 . . . . .</b>	<b>3.1750</b>
9/64 . . . . .	0.1406 . . . . .	3.5719
5/32 . . . . .	0.1563 . . . . .	3.9688
11/64 . . . . .	0.1719 . . . . .	4.3656
3/16 . . . . .	0.1875 . . . . .	4.7625
13/64 . . . . .	0.2031 . . . . .	5.1594
7/32 . . . . .	0.2188 . . . . .	5.5563
15/64 . . . . .	0.2344 . . . . .	5.9531
<b>1/4 . . . . .</b>	<b>0.2500 . . . . .</b>	<b>6.3500</b>
17/64 . . . . .	0.2656 . . . . .	6.7469
9/32 . . . . .	0.2813 . . . . .	7.1438
19/64 . . . . .	0.2969 . . . . .	7.5406
5/16 . . . . .	0.3125 . . . . .	7.9375
21/64 . . . . .	0.3281 . . . . .	8.3344
11/32 . . . . .	0.3438 . . . . .	8.7313
23/64 . . . . .	0.3594 . . . . .	9.1281
<b>3/8 . . . . .</b>	<b>0.3750 . . . . .</b>	<b>9.5250</b>
25/64 . . . . .	0.3906 . . . . .	9.9219
13/32 . . . . .	0.4063 . . . . .	10.3188
27/64 . . . . .	0.4219 . . . . .	10.7156
7/16 . . . . .	0.4375 . . . . .	11.1125
29/64 . . . . .	0.4531 . . . . .	11.5094
15/32 . . . . .	0.4688 . . . . .	11.9063
31/64 . . . . .	0.4844 . . . . .	12.3031
<b>1/2 . . . . .</b>	<b>0.5000 . . . . .</b>	<b>12.7000</b>

Inch Fraction	Decimal	Metric mm
33/64 . . . . .	0.5156 . . . . .	13.0969
17/32 . . . . .	0.5313 . . . . .	13.4938
35/64 . . . . .	0.5469 . . . . .	13.8906
9/16 . . . . .	0.5625 . . . . .	14.2875
37/64 . . . . .	0.5781 . . . . .	14.6844
19/32 . . . . .	0.5938 . . . . .	15.0813
39/64 . . . . .	0.6094 . . . . .	15.4781
<b>5/8 . . . . .</b>	<b>0.6250 . . . . .</b>	<b>15.8750</b>
41/64 . . . . .	0.6406 . . . . .	16.2719
21/32 . . . . .	0.6563 . . . . .	16.6688
43/64 . . . . .	0.6719 . . . . .	17.0656
11/16 . . . . .	0.6875 . . . . .	17.4625
45/64 . . . . .	0.7031 . . . . .	17.8594
23/32 . . . . .	0.7188 . . . . .	18.2563
47/64 . . . . .	0.7344 . . . . .	18.6531
<b>3/4 . . . . .</b>	<b>0.7500 . . . . .</b>	<b>19.0500</b>
49/64 . . . . .	0.7656 . . . . .	19.4469
25/32 . . . . .	0.7813 . . . . .	19.8438
51/64 . . . . .	0.7969 . . . . .	20.2406
13/16 . . . . .	0.8125 . . . . .	20.6375
53/64 . . . . .	0.8281 . . . . .	21.0344
27/32 . . . . .	0.8438 . . . . .	21.4313
55/64 . . . . .	0.8594 . . . . .	21.8281
<b>7/8 . . . . .</b>	<b>0.8750 . . . . .</b>	<b>22.2250</b>
57/64 . . . . .	0.8906 . . . . .	22.6219
29/32 . . . . .	0.9063 . . . . .	23.0188
59/64 . . . . .	0.9219 . . . . .	23.4156
15/16 . . . . .	0.9375 . . . . .	23.8125
61/64 . . . . .	0.9531 . . . . .	24.2094
31/32 . . . . .	0.9688 . . . . .	24.6063
63/64 . . . . .	0.9844 . . . . .	25.0031
<b>1 . . . . .</b>	<b>1.0000 . . . . .</b>	<b>25.4000</b>